PSC and FSI Statistics for the month of September 2015

			PSCO's	FSi	PSC
	PO,MMD, KANDLA	Kandla	Shri Sujit kumar Das , E&SS	0	5
1		Jamnagar	Shri Purno Chandra Majhi, E&SS	2	0
	PO,MMD, KOLKATA	Kolkata	Shri Vikrant Rai,E&SS	1	1
			Shri Ajay kumar Sinha , E&SS	0	NA
_			Capt Ravindra Sagar , NS	0	NA
2			Shri Satyanaryan Murty, E&SS	1	2
		Haldia	Shri Sudhir Shrivastava,E&SS	1	7
		Port Blair	Shri Ubaidu Rehman,E&SS	1	0
	PO,MMD, CHENNAI	Chennai	Shri Arbind Kumar Choudhary,E&SS	0	3
3			Shrì Gopi krishna C , E&SS	3	4
_		Visakha-patnam	Shri Jayanta Mukhopadhya , E&SS	1	4
		Tuticorin	Shri J Senthilkumar, E&SS	0	8
		Kochi	Capt P Misra , Dy NA	2	0
	DO BARAD MOCHI		Shri Lalu Natrajan	4	0
4	PO,MMD,KOCHI		Shri Kiran C S , E&SS	0	NA
		New Mangalore	Shri V V Paul,E&SS	1	7
	,		Shri Sajendra Oraon, E&SS	3	2
	,		Capt S I Abul kalam Azad , NS	. 0	0
	PO,MMD,	Mumbai	Shri G L Meena , E&SS	0	NA
5	MUMBAI		Shri Shrish Kumar, E&SS	2	1 1
	1		Shri Satish Kamath, E&SS	2	4
		Mormugao	Shri Bodh Raj,E&SS	2	6
	Total			26	54
	NUMBER OF VES	SELS DETAINED		2	3

FOREIGN VESSELS INSPECTED (TYPEWISE) UNDER PSC IN SEPTEMBER 2015

Sl. No.	TYPE OF SHIP	NO. OF INSPECTIONS	NO. OF SHIPS WITH DEFICIENCIES	NO. OF DETENTIONS
1.	Oil tanker	2	2	0
2.	Gas carrier	3	2	0
3.	Chemical tanker	9	8	0
4.	Bulk carrier	26	26	1
5.	Container ship	1	1	1
6.	Ro-ro cargo ship	1	1	0
7.	General cargo/multi purpose ship	8	7	0
8.	Wood-chip carrier	2	2	0
9.	Off shore service vessel	2	2	1
/• -	TOTAL	54	51	3

INDIAN VESSELS INSPECTED (TYPEWISE) UNDER FSI IN SEPTEMBER 2015

Sl. No.	TYPE OF SHIP	NO. OF INSPECTIONS	NO. OF SHIPS WITH DEFICIENCIES	NO. OF DETENTIONS
1.	Oil tanker	2	2	0
2.	Gas carrier	1	1	0
3.	Passenger Ship	6	6	0
4.	Bulk carrier	4	4	0
5.	Container ship	1	1	0
6.	Ro-ro cargo ship	1	1	0
7.	General cargo/multi purpose ship	5	6	0
8.	Off shore service vessel/ Tug	6	7	2
	TOTAL	26	26	2

The Most Common Deficiencies found on the vessels with respect to:-

- 1. Emergency fire pump operations.
- 2. Navigational equipments- Radar, MF/HF Equipment, SVDR defective
- 3. Cleanliness of Engine Room
- 4. Gas detection equipments defective.
- 5. Lack of familiarity with Enclosed space entry procedures.

(Aniruddha Chaki)

E&SS cum DDG(Tech)