MONTHLY FLAG AND PORT STATE INSPECTION REPORT JUNE 2016

A) INSPECTIONS OF FOREIGN SHIPS IN INDIA:

- I) TOTAL NUMBER OF INSPECTIONS: 39
- II) NUMBER OF SHIPS INSPECTED BASED ON IOMOU RISK FACTOR:

RISK LEVEL	VERY HIGH	HIGH	MEDIUM	LOW
NUMBER OF	03	02	16	18
SHIPS				

III) TYPE OF VESSEL INSPECTED:

TYPE	BULK - CARRIER	CHEMICAL TANKER	CONTAINER	GAS CARRIERS	OTHER CARGO	OIL TANKER
NUMBER	25,	06	1	1	2	4

- IV) NUMBER OF SHIPS DETAINED:03 (Sino 3, /infinity 1, Karaagac)
- V) TYPE OF SHIP DETAINED: Bulk Carrier, Oil Tanker.
- VI) NUMBER OF VESSEL WITHOUT DEFICIENCIES: 05
- VII) MOST COMMON DEFICIENCIES:

TYPE OF DEFICIENCY	NUMBER OF DEFICIENCY	MOST COMMON DEFICIENCY/DETAINABLE DEFICIENCY
Working Conditions	23	Electrical
Propulsion and auxiliary machinery	20	Other (Machinery)
Life saving appliances	10	Other (Life Saving)
Fire Safety	10	Fire detection and alarm system
Water /Weather Tight Conditions	14	Ventilators, air pipes, casings
Emergency System	12	Emergency, lighting, batteries and switches
Structural Conditions	09	Hull - corrosion
Safety of Navigation	08	Charts
Certificate & Documentation Documents	08	Oil record book

Mari

Detainable Deficiencies:

B) INSPECTION OF INDIAN SHIPS IN FOREIGN PORTS:

There are three Indian Flag Vessels reported detained in Port State Inspection for June 2016.

a)

Name of the Ship	Type of Ship	IMO No	Port Detained	MOU
Malaviya Seven	Offshore Service Vessel	9087312	Aberdeen	Paris

The Detainable deficiencies pertained to MLC 2006 including SEA , Wages, etc.,

b)

Name of the Ship	Type of Ship	IMO No	Port Detained	MOU
Nu Shi Nalini	Oil/Chemical	9619608	Bik	Iran
	Tanker			

The Detainable deficiency pertained to alarm system such as cargo pump temperature monitoring and UMS alarm in Engineers Cabin

c)

Name of the Ship	Type of Ship	IMO No	Port Detained	MOU
Jag Lavanya	Oil Tanker	9237412	Ama Anchorage,	U S Coast
1		ļ	LA	Guard

The Detainable deficiencies pertained to Fire Safety such as International shore-connection and Propulsion and Auxiliary Machinery such as Propulsion main engine

yelar.

C) FLAG STATE INSPECTIONS

- i) NUMBER OF VESSELS INSPECTED: 14
- ii) NUMBER OF VESSELS DETAINED: 1 (M.V Green Ocean 1)
- iii) TYPE OF VESSEL DETAINED: Passenger Ship
- iv) NUMBER OF VESSELS WITHOUT DEFICIENCIES: 03
- v) TYPES OF VESSELS INSPECTED:

TYPE OF VESSEL	TUG BOAT	OIL TANKER	GENERAL CARGO/MULTI- PURPOSE	PASSENGER SHIP	OTHER VESSEL TYPE	CHEMICALTANKER
NUMBER INSPECTED	04	01	02	01	05	01

vi) MOST COMMON DEFICIENCIES:

TYPE OF DEFICIENCY	NUMBER OF DEFICIENCY	MOST COMMON DEFICIENCY/DETAINABLE DEFICIENCY
Certificate & Documentation – Ship Certificates	02	Certificate & Documentation – Ship Certificates
ISM	02	ISM

vii) DETAINABLE DEFICIENCIES:

Name of the Ship	Type of Ship	IMO No	Port Detained	PSCO
M.V Green	Passenger Ship	8631697	Port Blair	Shri.Ubaidu
Ocean 1			-	Rehman

The detainable deficiency related to sailing vessel sailing without valid ISM documentation and certification.

zelai.

PSC AND FSI STATISTICS FOR THE MONTH OF JUNE 2016

			PSCO's	FSI	PSC
1	PO,MMD, KANDLA	Kandla / Sika	Shri Purno Chandra Majhi, E&SS	1	0
			Shri Sujit kumar Das , E&SS	0	0
		ļ	Shri Ajay kumar Sinha , E&SS	1	0
		Kolkata	Shri K M Rao , E&SS		0
2	PO,MMD, KOLKATA		Capt Ravindra Sagar , NS	1	0
			Shri Satyanaryan Murty, E&SS	0	1
		Haldia	Shri Aniruddha Chaki , E&SS	0	0
		Port Blair	Shri Ubaidu Rehman,E&SS	0 1 1 1 0	0
	· · · · · · · · · · · · · · · · · · ·	Ch	Shri Arbind Kumar Choudhary,E&SS	0	4
ا ر	DO MAND CHENNAL	Chennai	Shri Gopi krishna C, E&SS	0	4
3	PO,MMD, CHENNAI	Visakhapatnam	Shri Jayanta Mukhopadhya , E&SS	1	3
		Tuticorin		0	10
		Kochi	Capt P Misra , Dy NA	0	0
			Shri Lalu Natrajan	0	1
4	PO,MMD,KOCHI	Kocni	Shri Praveen Nair , E&SS	0	0
			Shri Kiran C S , E&SS	0	0
		New Mangalore	Shri V V Paul, E&SS	0	10
			Shri Sajendra Oraon, E&SS	7	0
			Capt S I Abul kalam Azad , NS	0	0.
		Mumbai	Shri S K Shrivastava, E&SS	0	0
5	PO,MMD, MUMBAI	Iviumai	Shri S. S Gadkar	0	0
			Shri Shrish Kumar, E&SS	0	0
			Shri Satish Kamath, E&SS	0	0
		Mormugao	Shri Bodh Raj,E&SS	0	6
	Tota	-		14	39
	NUMBER OF VESSI	ELS DETAINED		1	3

Mai.