

MONTHLY FLAG AND PORT STATE INSPECTION REPORT AUGUST 2016

(A) Port State Inspections (foreign ships in India):

- I) Total number of inspections : 46
II) Number of ships inspected based on IOMOU risk factor:

Risk level	Very high	High	Medium	Low
Number of ships	0	5	18	23

III) Type of vessel inspected :

Type	Bulk carrier	Chemical Tanker	Container	Gas carriers	General cargo	Oil Tanker	Wood chip carrier
Number	19	6	3	2	13	2	1

- IV) Number of ships detained : 01
V) Type of ship detained : GC/MPS
VI) Number of vessel without deficiencies : 12
VII) Most common deficiencies:

Type of deficiency	Number of deficiency
Working Conditions	25
Propulsion & Auxiliary Machines	19
Fire Safety	14
Safety Of Navigation	12
Life Saving Appliances	10
Certificate & Documentation-Documents	08
Water/Weather Tight Conditions	08
Pollution Prevention-Marpol Annex V	08

VIII) Detention of foreign ship in India :

There are 01 Indian flag vessels reported detained under Port State Inspection for August, 2016.

Name of the ship	Type of ship	IMO No	Date of Inspection	Port detained	PSCO
Bagawan	GC/MPS	8100105	26.08.16	Tuticorin	Shri J. Senthilkumar

The detainable deficiencies pertained to emergency fire pump and its pipes.

Vkai

(B) Inspection of Indian ships in foreign ports(abroad):

There are **01** Indian flag vessels reported detained in Port State Inspection (aboard) for August, 2016.

Name of the ship	Type of ship	IMO no	Date of Inspection	Port Detained	Mou
Ira iris	GC	9411458	25.08.2016	Colombo	IOMOU

Sr. No.	Type of deficiency	Deficiency code	Nature of deficiency
1.	Pollution Prevention-Marpol Annex I	14104	Oil Filtering Equipment
2.	Safety of Navigation	10114	Voyage Data Recorder (Vdr)/Simplified Voyage Data Recorder(S-Vdr)
3.	Safety of Navigation	10117	Echo Sounder
4.	Safety of Navigation	10116	Nautical Publications
5.	ISPS	16101	Security Related Defects
6.	Working and Living Conditions – Working Conditions	09223	Gangway, Accommodation-Ladder

(C) Flag State Inspections

- i) Number of vessels inspected : 22
- ii) Number of vessels detained : 01
- iii) Type of vessel detained : other type of ships
- iv) Number of vessels without deficiencies : 04

v) Types of vessels inspected :

Type Of Vessel	Tug Boat	Oil T	GC/ MPS	Other Vessel Type	Gas Carrier	BC	Contr.	OSV	High Speed Passenger Craft
Numbers Inspected	08	02	01	03	02	02	02	01	01

vkai

vi) Most Common Deficiencies:

Type Of Deficiency	Number Of Deficiency
Safety of Navigation	12
Life Saving Appliances	12
Working & Living Conditions-Working Conditions	11
Fire Safety	09
Water / Weather Tight Conditions	06
Certificate & Documentation- Ship Certificate	05
Pollution Prevention- Marpol Annex-I	05

There is 01 Vessel detained in Flag State Inspection for August, 2016

vii) Detainable Deficiencies:

Name of the Ship	Type of Ship	IMO No	Date of Inspection	Port Detained	PSCO
Seamec-III	OSV	8128339	09.08.2016	Mumbai	Shri Sudhir Shrivastava

The detainable deficiency pertained to

1. other (Marpol Annex I).cleanliness of engine room
2. 15 PPM Alarm arrangmts.

vkai

List of Authorised Surveyor

Sr.No	MMD	Name of the PSCO	FSI	PSC	Month of Inspection (August,2016)
			Authorisation		
1	Kandla	Shri P C Majhi,E&SS	Jul-14	Jul-14	FSI - 4
2		Shri Yogesh Jaisinghani,SS	Not yet authorised	Not yet authorised	NA
3		Capt A K Patel, NC	NA	NA	NA
1	Kolkata	Capt R Sagar, NS	Yes	Not qualified for PSC inspection	NA
2		Shri K M Rao, E&SS	Yes	Not qualified for PSC inspection	NA
3		Shri S K Das, E&SS	Yes	Yes	PSC-3
4		Shri S S Murty, E&SS	Yes	Yes	PSC-2
5		Shri A K Sinha , E&SS	Yes	Not qualified for PSC inspection	NA
6		Shri Ubaidu Rehman, E&SS	Yes	No	FSI-1
7		Shri Aniruddha Chaki, E&SS	Yes	No	FSI-1
8		Shri R R Subbarao, E&SS	NA	NA	NA
1		Capt S K Das , Dy NA	1998	1998	PSC-3
2	Chennai	Shri J Mukhopadhyaya, E&SS	Dec 05-Mar 08 and again from 01.07.2010 onwards	Dec 05-Mar 08 and again from 01.07.2010 onwards	PSC-3
3		Shri Arbind Kumar Choudhary, E&SS	May-11	May-11	FSI-1,PSC-2
4		Shri J Senthilkumar, E&SS	Jan-11	Nov-11	FSI-1,PSC-8
5		Shri Gopikrishna C, E&SS	15.06.2013	07.05.2013	PSC-4
6		Capt K S Pandian , NS	12.08.2016	Accompanies the PSC Surveyour for PSC inspection	NA
7		Shri J V S Bharathi, R I	Accompanies the PSC/FSI Surveyour for		NA
1	Mumbai	Shri S S Gadkar, Dy CS (I/C)	Yes	Yes	FSI-1
2		Capt S I Abul Kalam Azad, N S	Yes	Yes	NA
3		Shri Sajendra Oraon, E&SS	Yes	Yes	NA
4		Shri Shirish Kumar , E&SS	Yes	Yes	PSC-1 FSI-2
5		Shri Sudhir Kumar Shrivastava	Yes	Yes	FSI-6
6		Shri Nebu Oommen, Ship surveyour	No	No	NA
7		Shri B Mohapatra, R I	As a team member along with NS Or E&SS	As a team member along with NS Or E&SS	NA
8		Shri V R Padukone, R I	As a team member along with NS Or E&SS	As a team member along with NS Or E&SS	NA
1	Kochi	Shri L Natrajan	Yes	Yes	PSC-1
2		Shri Praveen Nair, E&SS	Yes	No	FSI-1
3		Shri Kiran C S , E&SS	Yes	Yes	PSC-2
4		Shri V V Paul, E&SS	Yes	Yes	FSI-4,PSC-12

VRai